

ATTORNEY'S DOCKET:
004578.1194

PATENT NO:
US 6,850,203 B1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Nicholas A. Schuneman, et al.
U.S. Patent No.: US 6,850,203 B1
Issue Date: February 1, 2005
Serial No.: 10/023,800
Filing Date: December 14, 2001
Confirmation No.: 3852
Title: *Decade Band Tapered Slot Antenna, and Method of Making Same*

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


Dear Sir:

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER 37 CFR § 1.322

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted,
BAKER BOTTS L.L.P.
Attorneys for Applicants


Bradley P. Williams
Reg. No. 40,227

Date: 9/26/06
Customer No.: 45507
Phone: (214) 953-6447

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Patent No.: US 6,850,203 B1
Dated: February 1, 2005
Inventor(s): Nicholas A. Schuneman, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On Title Page, References Cited, Other Publications, Page 2:

Column 2, Line 10, delete "COmpensation" and insert -- Compensation -- .

Column 2:

At Line 28, after delete "which:" and insert -- which ; -- .

Column 3:

At Line 35, after "each other by a thin" delete "layer." and insert -- layer -- .

Column 11:

At Line 13, after "the left port has a voltage" delete " V_x " and insert -- V_x -- and after "and current" delete " I_x " and insert -- I_x -- .

At Line 14, after "port has a voltage" delete " V_y " and insert -- V_y -- and after "and current" delete " I_y " and insert -- I_y -- .

At Line 42, after "the balun hole" delete "49." and insert -- 49 -- .

Mailing Address of Sender:
Baker Botts L.L.P.
2001 Ross Avenue, Suite 600
Dallas, Texas 75201-2980

Patent No. US 6,850,203 B1

Form PTO-1050

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Patent No.: US 6,850,203 B1
Dated: February 1, 2005
Inventor(s): Nicholas A. Schuneman, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 13:

At Line 57, delete "length l" and insert -- length *l* -- .

Column 14:

At Line 37, after "a respective" delete "[ABCD]matrix" and insert -- [ABCD] matrix -
- .

Column 18:

At Line 64, after "coupled to the metal" delete "plate." and insert -- plate -- .

Column 24:

At Line 20, after "said sheath being free of said shield" insert -- in the region of -- .

Mailing Address of Sender:

Baker Botts L.L.P.
2001 Ross Avenue, Suite 600
Dallas, Texas 75201-2980

Patent No. US 6,850,203 B1

Form PTO-1050